

**AMARAVATI DEVELOPMENT CORPORATION LIMITED**

**RFP for Refurbishment of Scrap Park-Construction, Supply, Installation and Commissioning of Waterfall type Water fountain and Video wall at Scrap & Sculpture Park Opp. Police Control Room, Vijayawada with 5 years of Operation & Maintenance.**

**RFP No: 21/CE/ADCL/2017 dated 03 - 10 - 2017.  
CORRIGENDUM-I, DT.20.10.2017**

S.No.	Page	Clause No.	As per RFP	As Corrected/Modified/Addition/Deletion
1	11	SECTION -II, clause -2	<p><b>DURATION OF CONTRACT</b> Duration for Construction, Supply, Installation and Commissioning of Water fall type Water fountain and Video wall at Scrap &amp; Sculpture Park Opp. Police Control Room, Vijayawada with 5 years of Operation &amp; Maintenance is 3 months + 5 years O&amp; M including 2 years Defect liability Period from the date of issue of Letter of Award.</p>	<p><b>DURATION OF CONTRACT</b> Duration for the work "Construction, Supply, Installation and Commissioning of Water fall type Water fountain and Video wall at Scrap &amp; Sculpture Park Opp. Police Control Room, Vijayawada with 5 years of Operation &amp; Maintenance" is 3 months for capital work from the date of issue of work order and 5 years for O&amp; M including 2 years Defect liability Period from the date of commissioning.</p>
2	12	Section-II clause-3.2.2	<p>Financial eligibility (specific to the bid): The bidder should have implemented similar nature of work to an aggregate of more than 2.00 Cr. in any one year in the last 5 years.</p>	<p>Financial eligibility (specific to the bid): The bidder/JV consortium should have implemented similar nature of work to an aggregate of more than 2.00 Cr. in any one year in the last 5 years.</p>

S.No.		Page	Clause No.	As per RFP		As Corrected/Modified/Addition/Deletion																													
3	19	21.2		<table border="1"> <thead> <tr> <th>Technical Criteria Assessment Parameter</th> <th>Marks break up</th> <th>Total Marks</th> </tr> </thead> <tbody> <tr> <td>1. The bidder/JV should have done Successful Completion of Similar nature of Works of min. 2 with 6 months O&amp;M with GoAP/ULB's/PSU's/MNC's/Reputed firms along with the experience certificates issued by the Concerned Competent authority in last 5 financial years.</td> <td>2 works- 25 marks 3 works-30marks 4 and above works-35 marks</td> <td>35</td> </tr> <tr> <td>2. The bidder/JV should have minimum value of satisfactorily completed similar works, as a Prime Contractor (in any one year) in last 5 financial years - 2.00Cr.</td> <td>1.cr. -20 marks 2 Cr.-30marks 3 Cr. and above-35 marks</td> <td>35</td> </tr> <tr> <td>3. The bidder/JV should have an average of three years annual turnover of Rs. 10.00 Crores in last three financial years.</td> <td>10.cr. -25 marks 20 Cr. and above -30 marks</td> <td>30</td> </tr> <tr> <td><b>Total</b></td> <td></td> <td><b>100</b></td> </tr> </tbody> </table>	Technical Criteria Assessment Parameter	Marks break up	Total Marks	1. The bidder/JV should have done Successful Completion of Similar nature of Works of min. 2 with 6 months O&M with GoAP/ULB's/PSU's/MNC's/Reputed firms along with the experience certificates issued by the Concerned Competent authority in last 5 financial years.	2 works- 25 marks 3 works-30marks 4 and above works-35 marks	35	2. The bidder/JV should have minimum value of satisfactorily completed similar works, as a Prime Contractor (in any one year) in last 5 financial years - 2.00Cr.	1.cr. -20 marks 2 Cr.-30marks 3 Cr. and above-35 marks	35	3. The bidder/JV should have an average of three years annual turnover of Rs. 10.00 Crores in last three financial years.	10.cr. -25 marks 20 Cr. and above -30 marks	30	<b>Total</b>		<b>100</b>	<table border="1"> <thead> <tr> <th>Technical Criteria Assessment Parameter</th> <th>Marks break up</th> <th>Total Mark</th> </tr> </thead> <tbody> <tr> <td>1. The bidder/JV should have done Successful Completion of Similar nature of Works of min. 2 with 6 months O&amp;M with GoAP/ULB's/PSU's/MNC's/Reputed firms along with the experience certificates issued by the Concerned Competent authority in last 5 financial years.</td> <td>2 works - 24.5 marks 3 works -30marks 4 and above works -35 marks</td> <td>35</td> </tr> <tr> <td>2. The bidder/JV should have minimum value of satisfactorily completed similar works, as a Prime Contractor (in any one year) in last 5 financial years – Rs.2.00Cr.</td> <td>=Rs.2.00Cr. – 24.5 marks &gt;Rs.2.00 Cr &amp; ≤Rs.3.00 Cr.- - 30marks &gt;Rs.3.00 Cr. -35 marks</td> <td>35</td> </tr> <tr> <td>3. The bidder/JV should have an average of three years annual turnover of Rs. 10.00 Crores in last three financial years.</td> <td>=Rs.10.00cr. -21 marks &gt;Rs.10.00 Cr. to ≤Rs.15.00Cr. - 25 marks &gt;Rs.15.00 Cr. - 30 marks</td> <td>30</td> </tr> <tr> <td><b>Total</b></td> <td></td> <td><b>100</b></td> </tr> </tbody> </table>	Technical Criteria Assessment Parameter	Marks break up	Total Mark	1. The bidder/JV should have done Successful Completion of Similar nature of Works of min. 2 with 6 months O&M with GoAP/ULB's/PSU's/MNC's/Reputed firms along with the experience certificates issued by the Concerned Competent authority in last 5 financial years.	2 works - 24.5 marks 3 works -30marks 4 and above works -35 marks	35	2. The bidder/JV should have minimum value of satisfactorily completed similar works, as a Prime Contractor (in any one year) in last 5 financial years – Rs.2.00Cr.	=Rs.2.00Cr. – 24.5 marks >Rs.2.00 Cr & ≤Rs.3.00 Cr.- - 30marks >Rs.3.00 Cr. -35 marks	35	3. The bidder/JV should have an average of three years annual turnover of Rs. 10.00 Crores in last three financial years.	=Rs.10.00cr. -21 marks >Rs.10.00 Cr. to ≤Rs.15.00Cr. - 25 marks >Rs.15.00 Cr. - 30 marks	30	<b>Total</b>		<b>100</b>
Technical Criteria Assessment Parameter	Marks break up	Total Marks																																	
1. The bidder/JV should have done Successful Completion of Similar nature of Works of min. 2 with 6 months O&M with GoAP/ULB's/PSU's/MNC's/Reputed firms along with the experience certificates issued by the Concerned Competent authority in last 5 financial years.	2 works- 25 marks 3 works-30marks 4 and above works-35 marks	35																																	
2. The bidder/JV should have minimum value of satisfactorily completed similar works, as a Prime Contractor (in any one year) in last 5 financial years - 2.00Cr.	1.cr. -20 marks 2 Cr.-30marks 3 Cr. and above-35 marks	35																																	
3. The bidder/JV should have an average of three years annual turnover of Rs. 10.00 Crores in last three financial years.	10.cr. -25 marks 20 Cr. and above -30 marks	30																																	
<b>Total</b>		<b>100</b>																																	
Technical Criteria Assessment Parameter	Marks break up	Total Mark																																	
1. The bidder/JV should have done Successful Completion of Similar nature of Works of min. 2 with 6 months O&M with GoAP/ULB's/PSU's/MNC's/Reputed firms along with the experience certificates issued by the Concerned Competent authority in last 5 financial years.	2 works - 24.5 marks 3 works -30marks 4 and above works -35 marks	35																																	
2. The bidder/JV should have minimum value of satisfactorily completed similar works, as a Prime Contractor (in any one year) in last 5 financial years – Rs.2.00Cr.	=Rs.2.00Cr. – 24.5 marks >Rs.2.00 Cr & ≤Rs.3.00 Cr.- - 30marks >Rs.3.00 Cr. -35 marks	35																																	
3. The bidder/JV should have an average of three years annual turnover of Rs. 10.00 Crores in last three financial years.	=Rs.10.00cr. -21 marks >Rs.10.00 Cr. to ≤Rs.15.00Cr. - 25 marks >Rs.15.00 Cr. - 30 marks	30																																	
<b>Total</b>		<b>100</b>																																	

S.No.	Page	Clause No.	As per RFP	As Corrected/Modified/Addition/Deletion																																
4	36& 37	Annexure -II (A)	<p><b>2. Video Wall:</b></p> <table border="1"> <tr> <td><b>Interface:</b></td> <td></td> </tr> <tr> <td>Speakers</td> <td>Suitable</td> </tr> <tr> <td>Touch Surface</td> <td>Tempered Anti-Glare Glass</td> </tr> <tr> <td><b>Cabinet Engineering</b></td> <td></td> </tr> <tr> <td>Response Time</td> <td>6 ms</td> </tr> <tr> <td>Inlay Mode</td> <td>Built-in</td> </tr> <tr> <td>Mounting</td> <td>Wall</td> </tr> <tr> <td>Built in Wifi</td> <td>Required</td> </tr> </table>	<b>Interface:</b>		Speakers	Suitable	Touch Surface	Tempered Anti-Glare Glass	<b>Cabinet Engineering</b>		Response Time	6 ms	Inlay Mode	Built-in	Mounting	Wall	Built in Wifi	Required	<p><b>2. Video Wall:</b></p> <table border="1"> <tr> <td><b>Interface:</b></td> <td></td> </tr> <tr> <td>Speakers</td> <td>Deleted</td> </tr> <tr> <td>Touch Surface</td> <td>Deleted</td> </tr> <tr> <td><b>Cabinet Engineering</b></td> <td></td> </tr> <tr> <td>Response Time</td> <td>Deleted</td> </tr> <tr> <td>Inlay Mode</td> <td>Deleted</td> </tr> <tr> <td>Mounting</td> <td>Floor mounting along with necessary structure &amp; ACP</td> </tr> <tr> <td>Built in Wifi</td> <td>Deleted</td> </tr> </table> <p><b>Please refer Addendum-I for additional information</b></p>	<b>Interface:</b>		Speakers	Deleted	Touch Surface	Deleted	<b>Cabinet Engineering</b>		Response Time	Deleted	Inlay Mode	Deleted	Mounting	Floor mounting along with necessary structure & ACP	Built in Wifi	Deleted
<b>Interface:</b>																																				
Speakers	Suitable																																			
Touch Surface	Tempered Anti-Glare Glass																																			
<b>Cabinet Engineering</b>																																				
Response Time	6 ms																																			
Inlay Mode	Built-in																																			
Mounting	Wall																																			
Built in Wifi	Required																																			
<b>Interface:</b>																																				
Speakers	Deleted																																			
Touch Surface	Deleted																																			
<b>Cabinet Engineering</b>																																				
Response Time	Deleted																																			
Inlay Mode	Deleted																																			
Mounting	Floor mounting along with necessary structure & ACP																																			
Built in Wifi	Deleted																																			

*[Signature]*  
**CHIEF ENGINEER**  
 20/10/17